

## Club 100: The Model 100 User Group

P.O. Box 23438, Pleasant Hill, CA 94523-0438 Richard Hanson, Proprietor (925) 932-8956, fax (925) 937-5039 www.club100.org rick@Club100.org

Thank you for purchasing the new MOMBO Lite Option ROM carrier board. Unlike the MOMBO, the MOMBO Lite comes without a PROM attached. You will find information about the PROM you need at the Club 100 web site, in the ROMware category of the library.



In the photo at the left (from top to bottom) you see the raw MOMBO board, followed by a "trimmed" MOMBO board, some jumper stock, a strip of extraction ribbon—used to remove a MOMBO from the Molex socket in a Model 100, 102 or 200, and a stand-off/spacer.

**NOTE:** Do not insert a MOMBO into the Option ROM socket of a Model 100, 102 or 200 without the extraction ribbon and stand-off/spacer attached ... or you are not going to be able to remove the MOMBO without damage. <u>Trust me</u>!

Below is the bottom-side and top-side of a completed MOMBO. The extraction ribbon is stuck to the underside of the MOMBO board with double-sided tape, as is the stand-off/spacer.

